


188

2

RESURVEY, E. BDY. OF T. 13 S., R. 21 E.

| CHAINS | |
|---|---|
| | From this point the original ¼ sec. cor. of secs. 31 and 36, bears N. 84°33' E., 40.53 chs. dist.; marked by a mound of earth and stone. I destroy this monument. |
| | Ascend 55 ft. over SW. slope. |
| 46.10 | Spur, slopes SE.; descend 130 ft. over broken NE. slope. |
| 74.30 | Wash, course W.; ascend 100 ft. over S. slope. |
| 79.90 | Spur, slopes SW.; descend gradual NW. slope. |
| 80.00 | Point for the cor. of secs. 25 and 36. |
| | Set an iron post, 28 ins. long, 2½ ins. diam., 5 ins. in the ground to bedrock, with brass cap mkd. T13S \| R21E \| R22E \| S 25 \| S 36 \| 1961 |
| | Raise a mound of stone, 5 ft. base, around post to top. |
| | From this point the original cor. of secs. 25, 30, 31, and 36, bears N. 83°15' E., 41.42 chs. dist.; marked by a mound of stone, 3 ft. base, 1 ft. high. I destroy this monument. |
| | Land, low broken mountains. Soil, sandy and gravelly, with some clayloam. Timber, scattering ironwood and paloverde in the washes. Undergrowth, greasewood, sage, and cacti. |
| | North, along the E. bdy. of sec. 25. |
| | Descend 160 ft. over NW. slope, through scattering undergrowth. |
| 12.70 | Enter Carrizo Wash, course NE. |
| 12.90 | Jeep road, bears NE. and SW. |
| 13.10 | Leave wash; ascend 150 ft. over broken SW. slope. |
| 21.60 | Spur, slopes SE.; descend 120 ft. over NE. slope. |
| 26.30 | Wash, 20 lks. wide, course SE.; ascend 250 ft. over S. slope. |
| 37.90 | Spur, slopes NE.; descend 60 ft. over NW. slope. |
| 40.00 | Point for the ¼ sec. cor. of sec. 25. |
| | Set an iron post, 28 ins. long, 2½ ins. diam., 12 ins. in the ground to bedrock, with brass cap mkd. 1/4 \| S 25 \| R21E \| R22E \| T13S \| 1961 |
| | Deposit a stone, 6 x 3 x 2 ins., mkd. X, at base of iron post and raise a mound of stone, 3 ft. base, around post to top. There is no evidence of the original ¼ sec. cor. of secs. 25 and 30. |

**PAGE SURVEY PLOT** N up

No reliable locations available for this page.

0 located symbols · 13 calls without a location

Numbers match the text table; only this scan page is shown.

| # | Ch | Type | Field Note Text | Elev | Links | Lat/Lon | GCDB |
|---|---|---|---|---|---|---|---|
| 1 | | | RESURVEY, E. BDY. OF T. 13 S., R. 21 E. | | | | |
| 2 | | ▲ | **Cor. Secs. 1-6-31-36 · From this point the original ¼ sec. cor. of secs. 31 and 36, bears N. 84°33' E., 40.53 chs. dist.; marked by a mound of earth and stone. I destroy this monument.** | | | | 100100 |
| 3 | | ● | Ascend 55 ft. over SW. slope. | | | | |
| 4 | 46.10 | ● | Spur, slopes SE.; descend 130 ft. over broken NE. slope. | | | | |
| 5 | 74.30 | ● | Wash · Wash, course W.; ascend 100 ft. over S. slope. | | | | |
| 6 | 79.90 | ● | Spur, slopes SW.; descend gradual NW. slope. | | | | |
| 7 | 80.00 | ▲ | **Cor. Secs. 25-30-31-36 · Point for the cor. of secs. 25 and 36. Set an iron post, 28 ins. long, 2½ ins. diam., 5 ins. in the ground to bedrock, with brass cap mkd. T13S R21E\|R22E S 25\| S 36\| 1961 Raise a mound of stone, 5 ft. base, around post to top. From this point the original cor. of secs. 25, 30, 31, and 36, bears N. 83°15' E., 41.42 chs. dist.; marked by a mound of stone, 3 ft. base, 1 ft. high. I destroy this monument. Land, low broken mountains. Soil, sandy and gravelly, with some clayloam. Timber, scattering ironwood and paloverde in the washes. Undergrowth, greasewood, sage, and cacti. North, along the E. bdy. of sec. 25. Descend 160 ft. over NW. slope, through scattering undergrowth.** | | | | 100200 |
| 8 | 12.70 | ● | Carrizo Wash · Enter Carrizo Wash, course NE. | | | | |
| 9 | 12.90 | ■ | Jeep road, bears NE. and SW. | | | | |
| 10 | 13.10 | ● | wash · Leave wash; ascend 150 ft. over broken SW. slope. | | | | |
| 11 | 21.60 | ● | Spur, slopes SE.; descend 120 ft. over NE. slope. | | | | |
| 12 | 26.30 | ● | Wash · Wash, 20 lks. wide, course SE.; ascend 250 ft. over S. slope. | | | | |
| 13 | 37.90 | ● | Spur, slopes NE.; descend 60 ft. over NW. slope. | | | | |
| 14 | 40.00 | △ | **¼ Cor. Sec. 25 N · Point for the ¼ sec. cor. of sec. 25. Set an iron post, 28 ins. long, 2½ ins. diam., 12 ins. in the ground to bedrock, with brass cap mkd. 1/4\| S 25\| R21E\|R22E T13S 1961 Deposit a stone, 6 x 3 x 2 ins., mkd. X, at base of iron post and raise a mound of stone, 3 ft. base, around post to top. There is no evidence of the original ¼ sec. cor. of secs. 25 and 30.** | | | | 640300 |

# Field Note Summary & Terrain Fraud Profile

## SURVEY RUN SUMMARY

Amador County, CA

**START CORNER (ch 0.00)**

¼ corner, Sec. 25

GCDB code: 640300

**NOTABLE CALLS ALONG RUN**

ch 12.70 Carrizo Wash — Enter Carrizo Wash, course NE.
ch 13.10 wash — Leave wash; ascend 150 ft. over broken SW. slope.
ch 26.30 Wash — Wash, 20 lks. wide, course SE.; ascend 250 ft. over S. slope.
ch 74.30 Wash — Wash, course W.; ascend 100 ft. over S. slope.

**END CORNER (ch 80.00)**

Corner, Secs. 25, 30, 31 & 36

GCDB code: 100200

11 total calls · 0 geo-located · 0 with elevation

## TERRAIN FRAUD ANALYSIS

**NONE**

0 flags · 0 verifications

## ELEVATION PROFILE

Run Geolocate on this document to generate the elevation profile.